Flasher LT Quick Start Instructions
## For Windows XP

BOSCH

Step 1:

Connect the Flasher LT cable to a USB port on your PC. Windows will detect the Flasher LT automatically by plug-and-play

Step 2:

The *Found New Hardware Wizard* will pop-up automatically. Select "No, not this time" and click next. Then click "Install from a list of specific location" and click next.

Step 3:

Insert the Flasher LT drivers CD, make sure "Search removable media" is selected, and click next.

Step 4:

The *Found New Hardware Wizard* will install all necessary drivers. A dialog box may pop-up to indicate that Flasher LT has not passed Windows Logo testing. Click "Continue Anyway".

*Instructions for Windows 2000 on other side*

BOSCH

Step 1:
Connect the Flasher LT cable to a USB port on your PC. Windows will detect the Flasher LT automatically by plug-and-play.


Step 2:
The *Found New Hardware Wizard* will pop-up automatically. Select Next. Then Click "Search for a Suitable Driver for my Device" and click next.


Step 3:
Insert the Flasher LT drivers CD, make sure the CD-ROM drives is selected, and click next.

Step 4:
The *Found New Hardware Wizard* will find the driver on the CD-ROM. Click Next and it will install all of the necessary drivers.

Instructions for Windows XP on other side